


# Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.

# **Energy efficiency rating for this property**

This property's current energy rating is D.



Properties are given a rating from A+ (most efficient) to G (least efficient).

Properties are also given a score. The larger the number, the more carbon dioxide (CO2) your property is likely to emit.

# How this property compares to others

Properties similar to this one could have ratings:

If newly built

32 B

If typical of the existing stock

128 F

# Breakdown of this property's energy performance

Main heating fuel	Natural Gas
Building environment	Heating and Natural Ventilation
Assessment level	3
Building emission rate (kgCO2/m2 per year)	79.15
Primary energy use (kWh/m2 per year)	466

# **Recommendation report**

Guidance on improving the energy performance of this property can be found in the  $\underline{\text{recommendation}}$   $\underline{\text{report (/energy-certificate/2895-3581-2643-1220-7756)}}$ .

#### Who to contact about this certificate

#### Contacting the assessor

If you're unhappy about your property's energy assessment or certificate, you can complain to the assessor who created it.

Assessor's name Julian Clarke
Telephone 01924 669941

Email <u>epc@compliance365.co.uk</u>

#### Contacting the accreditation scheme

If you're still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation scheme Elmhurst Energy Systems Ltd

Assessor's ID EES/028250
Telephone 01455 883 250

Email <u>enquiries@elmhurstenergy.co.uk</u>

About this assessment

Employer Compliance 365
Employer address 6 Mariner Court

Assessor's declaration The assessor is not related to the owner of the

property.

Date of assessment 1 June 2023 Date of certificate 8 June 2023

# Energy performance certificate (EPC) recommendation report

The George Inn 55 St James Street DAVENTRY NN11 4AG Report number **2895-3581-2643-1220-7756** 

Valid until 7 June 2033

# **Energy rating and EPC**

This property's current energy rating is D.

For more information on the property's energy performance, see the EPC for this property.

#### Recommendations

Make these changes to improve the property's energy efficiency.

Recommended improvements are grouped by the estimated time it would take for the change to pay for itself. The assessor may also make additional recommendations.

Each recommendation is marked as low, medium or high. This shows the potential impact of the change on reducing the property's carbon emissions.

# Changes that pay for themselves within 3 years

Recommendation	Potential impact
Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.	Low
Add time control to heating system.	Medium
Add optimum start/stop to the heating system.	Medium
The default heat generator efficiency is chosen. It is recommended that the heat generator system be investigated to gain an understanding of its efficiency and possible improvements.	Low
Some walls have uninsulated cavities - introduce cavity wall insulation.	Medium
Consider replacing T8 lamps with retrofit T5 conversion kit.	Low
Some windows have high U-values - consider installing secondary glazing.	Medium
Add weather compensation controls to heating system.	Medium
Some loft spaces are poorly insulated - install/improve insulation.	Medium
Add local time control to heating system.	Medium
Some solid walls are poorly insulated - introduce or improve internal wall insulation.	Medium
Consider switching from gas to biomass.	High
Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Medium
Changes that pay for themselves within 3 to 7 years	
Recommendation	Potential impact
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	Low
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium
Consider installing an air source heat pump.	Medium
Consider installing a ground source heat pump.	Medium

Recommendation		Potential impact	
Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or exterior.		Medium	
Changes that pay for themse	lves in more than 7 years		
Recommendation		Potential impact	
Roof is poorly insulated. Install or improve	e insulation of roof.	Medium	
Consider installing building mounted wind	turbine(s).	Low	
Consider installing solar water heating.		Low	
Consider installing PV.		Low	
Property and report details			
Report issued on	8 June 2023		
Total useful floor area	191 square metres		
Building environment	Heating and Natural Ventilation		
Calculation tool	DesignBuilder Software Ltd, DesignBuild v7.1.4, SBEM, v6.1.e.0	DesignBuilder Software Ltd, DesignBuilder SBEM, v7.1.4, SBEM, v6.1.e.0	

# Assessor's details

Assessor's name	Julian Clarke
Telephone	01924 669941
Email	epc@compliance365.co.uk
Employer's name	Compliance 365
Employer's address	6 Mariner Court
Assessor ID	EES/028250
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Elmhurst Energy Systems Ltd