Energy performance certificate (EPC) recommendation report

The Salix Beach Café Small Hope Beach Esplanade SHANKLIN PO37 6BG Report number 6743-9665-5757-4130-8319

Valid until **24 August 2032**

Energy rating and EPC

This property's energy rating is B.

For more information on the property's energy performance, see the EPC for this property.

Recommendations

Changes that may pay for themselves within 3 years

Recommendation	Potential impact on carbon emissions
Add time control to heating system.	Medium
Add optimum start/stop to the heating system.	Medium
Consider replacing T8 lamps with retrofit T5 conversion kit.	Medium
The default heat generator efficiency is chosen. It is recommended that the heat generator system be investigated to gain an understanding of its efficiency and possible improvements.	High
Add local temperature control to the heating system.	Medium
Add weather compensation controls to heating system.	Medium
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	Low
Add local time control to heating system.	Medium
	Medium
Changes that may pay for themselves within 3 to 7 years	Medium Potential impact on carbon emissions
Changes that may pay for themselves within 3 to 7 years Recommendation Carry out a pressure test, identify and treat identified air leakage. Enter result in	Potential impact on
Changes that may pay for themselves within 3 to 7 years Recommendation Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Potential impact on carbon emissions
Changes that may pay for themselves within 3 to 7 years Recommendation Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Consider installing an air source heat pump.	Potential impact on carbon emissions Medium
Add local time control to heating system. Changes that may pay for themselves within 3 to 7 years Recommendation Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Consider installing an air source heat pump. Consider installing a ground source heat pump. Changes that may pay for themselves in over 7 years	Potential impact on carbon emissions Medium Medium
Changes that may pay for themselves within 3 to 7 years Recommendation Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Consider installing an air source heat pump. Consider installing a ground source heat pump.	Potential impact on carbon emissions Medium Medium
Changes that may pay for themselves within 3 to 7 years Recommendation Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Consider installing an air source heat pump. Consider installing a ground source heat pump. Changes that may pay for themselves in over 7 years	Potential impact on carbon emissions Medium Medium High
Changes that may pay for themselves within 3 to 7 years Recommendation Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Consider installing an air source heat pump. Consider installing a ground source heat pump. Changes that may pay for themselves in over 7 years Recommendation	Potential impact on carbon emissions Medium Medium High Potential impact on carbon emissions

Property and report details

Report issued on	25 August 2022
Total useful floor area	105 square metres
Building environment	Heating and Natural Ventilation
Calculation tool	CLG, iSBEM, v6.1.b, SBEM, v6.1.b.0

Assessor's details

Stephen Hendey
IOW EPC SERVICES
22 Coronation Avenue, Northwood, Cowes, Isle of Wight
STRO031378
The assessor is not related to the owner of the property.
Stroma Certification Ltd